National Association of Lift Makers



33/34 Devonshire Street

London W1N 1RF

Director D M Fazakerley

telephone:

071-935 3013

fax:

071-935 3321

To: All Members

cc: 7

The Quality and Technical Committee (Code No: 1583)

8 December 1992

Dear Sir

SAFETY CHECK ON SYNCHRONISATION OF ADX 2 PANEL SIDE OPENING DOORS

I have received the enclosed information from Kone Lifts Ltd and would ask that members be guided accordingly.

Yours faithfully

D M Fazakerley

Director



4th December 1992

Our Ref: AJS/JMH

Your Ref:

National Association of Lift Makers 33-34 Devonshire Street London W1N 1RF

For the attention of Mr D Fazakerley

Dear David

Please circulate the attached Safety Notice to the membership and other relevant parties who could be affected.

This information has been passed to us from our factory in Germany.

At this time we do not have any experience of the problem occurring in this country, however it is better to be cautious in such matters.

Yours sincerely

Adrian Shiner

Technical Manager

Encl:

A:LAS4-12

KONE LIFTS Safety check on Synchronisation of ADX 2 Panel					CODE: SN 03.13.01		
					Page 1 of 9		
LTD	Side Opening Doors				SAFETY CATEGORY	A	
DEPT. CENTRAL ENG	DATE 4.12.92	COMPILED BY A J SHINER	CHECKED A J SHINER	APPROVED	ISSUE A		

- 1. Please refer to the attached information sheets.
- 2. The condition of the synchronisation rollers and locking plate must be checked at the next service visit.
- 3. If the door requires replacement parts, these can be obtained from the Central Stores at Kone Lifts, 168-170 Wellington Road South, Hounslow, Middlesex, TW4 5JN



EXPRESS INFORMATION

Ari Ketonen / HAT

10.11.1992

SN 03.13.01 Sheet 2 Of 9

EXPRESS INFORMATION

ADX2 CAR DOORS

A dangerous failure with ADX2 panels and synchronisation has been found. The slower panel may be open and the fast panel is closed while the elevator is running. This is caused by two simultaneous failures.

- 1. The locking plate on the fast door panel is not installed during the installation and
- 2. The roller at synchronisation rod has fallen out.

ACTIONS

- 1. Check that all ADX2 CAR DOORS have the locking plate installed at the rear edge of the fast panel. If not get it done immediately. The order mark is 61863H02 from HDF Hannover FAX 49-511-2148147
- Check that the shaft of rollers, and rollers are properly fixed on the synchronisation rod. If they are loose or worn out order new rod from HDF Hannover order marks: ADX2L rod 61527G13 ADX2R rod 61527G14

This note concerns all ADX2 car doors.

The fixing of door panel locking plate is shown in updated AM 3.13.21 issue A pages 7&8.

AR 3.14.2 issue B pages 18-19 & 22-23


Best regards

Harri Ojala

Tage Lindfors

9 DOOR PANELS

SN 03.13.01 Sheet 3 of 9



- Install the synchronization rod (3) onto the top track with loosely tightened screw joints.
- Drive the car in level with the landing door.
- Place the unmounted hangerplate (4) into the track.
- Install the "slow" door panel to the hangerplate with loosely tightened screws (1) and (2). Note! The screw (1) has to be total inscrewed but not final tightened. The screw (1) has a function as an axle when aligning the door panel.
- Install the bottom guide (5).
- Adjust the door panel in line with the side post. Tighten the screws (1) and (2).
- Drive the car in position 30...35 cm above the landing door sill.
- Lift in the "fast" door panel, up and behind the hanger plate.
- Install the bottom guide.
- Drive the car in position 30...40 cm under the landing door sill, so the coupler is below the rollers.
- Install the "fast" door panel onto the hanger plate with loosely tightened screws (1) and (2).
- Align the door panel against the slam post (must be checked from inside car). Tighten the screws (1) and (2).

SN 03.13.01 Sheet 4 of 9


- Put in the syncronization rod rollers into the door panel tracks, gently bending the rod.
- The both door panels must be in line with the side post when the door is open and when the door is closed must the gap between the "fast" door panel and the slam post be 1...2 mm. Adjust from the "fast" door panel end rubber buffers.
- Open and close the door a few times and then tighten the syncronization rod screw joints when the door is in open position.
- Install the lock plate (7) to the "fast" door panel.

10 DOOR CONTACT

- Check that (and adjust) the bridge beging closing the circuit when the gap between the "fast" door panel and the slam post is 4 mm.

11 DOOR COUPLER

11.1 RUNNING CLEARANCE




- Run the car to each landing door and check up the running clearance as shown in the figure.
- Adjust the landing door lock rollers if needed, see the landing door instruction.

NOTE!

The door coupler is adjusted at the factory and normal there is no need to readjusting at site. However, it is recommended to check the factory adjustments before running the car, as mentioned in paragraph 11.2, page 9.

Electrification and commissioning of the door drive, see AME (AM2) instructions. The checking of running clearance can also be worked out with non-electrified car door operator, see paragraph 11.3, page 9.



POS.	PART NUMBER 61340G 61360G 61341G 61361G	DESCRIPTION ADX2L Slow door panel ADX2L Slow door panel ADX2R Slow door panel ADX2R Slow door panel	REMARKS Zincal, See table! Stainless steel, See table! Zincal, See table! Stainless steel, See table!	A) 1 1 1 1	B)
2.	61342G 61362G 61352G 61372G 61347G 61367G 61363G 61353G 61373G 61348G	ADX2L Fast door panel ADX2R Fast door panel	Zincal, without photocell, See table! Stainless steel, without photocell, See table! Zincal, with photocell, See table! Stainless steel, with photocell, See table! Zincal, with safety edge, See table! Stainless steel, with safety edge, See table! Zincal, without photocell, See table! Stainless steel, without photocell, See table! Zincal, with photocell, See table! Stainless steel, with photocell, See table! Stainless steel, with safety edge, See table! Stainless steel, with safety edge, See table!	1 1 1 1 1 1 1 1 1	

OS. 1 and 2;G							
HH =	LL = Clear opening width						
Clear opening height	VAR	700	800	900	1000	1100	
1900	G01	G02	G03	G04	G05	G06	
2000	G11	G12	G13	G14	G15	G16	
2100	G21	G22	G23	G24	G25	G26	


17-21					
3.	61863H02	Safety plate		1	
4.	61521G	Guide shoe, complete	with safety edge, See table!	2	
	61522G	Guide shoe, complete	standard door panel, See table!	2	
5.	61523H01	Guide shoe	• If I is a subspace to specific	4	4
6.	61524H02	Buffer			
7.	257615	Antidrumming plate	Terodem 2002 100x1000		
	257616	Antidrumming plate	Terodem 2002 150x1000		
	257617	Antidrumming plate	Terodem 2002 200x 1000		

		LL = Clear opening width						
POS.	PART NUMBER	VAR	700	800	900	1000	1100	
4.	61521G	G01	G02	G03	G04	G05	G06	
	61522G	G01	G02	G03	G04	G05	G06	

A) Number of parts in one assembly

B) Recommended number of stocked spare parts for 1...6 lifts

ADX2L SYNCRONISATION LEVER 61527G13 ADX2R SYNCRONISATION LEVER 61527G14



POS.	PART NUMBER	DESCRIPTION	REMARKS	A)	B)
1.	61579G01	Lever	for ADX2L	1	1
	61579G02	Lever	for ADX2R	1	1
2. '	61847H02	Bearing		2	_
3.	256514	Canoe clip Form 1	354-0824-0000 FASTEX	2	
4.	256546	Bearing Form T	41/19/12,14,20,071 IGLIDUR	2	
5.	256517	Buffer 4x15x60	Teasmoll 700 white	1	
6.	359391H03	Roller		2	2
7.	61536H02	Distance washer		2	
8.	104489	Locking ring	12x1 DIN471	2	
9.	257005	Pin	LG 12x50 IT10	1	
10.	61847H03	Distance plate		1	
11.	60107G01	Double nut		1	
12.	257161	Spring	11x36 DIN7346	2	
13.	249422	Screw	M8x60 DIN912	2	
14.	257084	Washer	12x18x1,2 DIN988	2	

A) Number of parts in one assembly

B) Recommended number of stocked spare parts for 1...6 lifts

