

Lift and Escalator Industry Association

33-34 Devonshire Street London WIN 1RF Tel: 0171 935 3013 Fax: 0171 935 3321

To: All Members

c.c. The Quality & Technical Committee

14 February 1997

Dear Sir

KONE LIFTS LTD TYPE MR12 BRAKE BOW ARMS


I enclose a Safety Notice issued by the above company relating to their type MR12 Brake Bow Arms. Will members please take note and be guided accordingly.

Yours faithfully

D M Fazakerley

Director





,	Subject				CODE: SN 04.05.16
KONE LIFTS	MR12 BRAKE BOW ARMS.				Page 1 of 5
LID					SAFETY CATEGORY A
DEPT. TECH.SUPP	DATE 7.2.97	COMPILED BY A J Shiner	CHECKED V J Kaura	APPROVED	ISSUE A

Please note the contents of the attached FL 4.8.1 and act accordingly.

(((

KO N E

FIELD LETTER

FL-4.8.1

Page: 1

Compiled by: KCO/P. Eagling

Changed by:

Checked by: SAB/ Arrivabene Approved by: FIS/ J. Reilio Date: 7.1.1997

© KONE Corporation

Product code: MR12 Drawing no:

Issue: -No of Pages: 4

Language: en SW: FM5.0 Win

MR12 BRAKE BOW ARMS

1 PRODUCTS AFFECTED

There have been some cases of the brake bow arm of the MR12 gear cracking or breaking. The cases are very rare approximately 1 in 15,000.

As each gear has two brake bows, the hazard is very low. As a precaution, it has been decided that there should be a visual inspection for each gear during the next planned maintenance visit.

2 DESCRIPTION OF THE PROBLEM

2.1 Symptoms and nature of the safety risk

In the reported cases of the cracked and broken brake bow arms the fracture has occurred in the position marked A in the diagram 1 in Appendix 1.

In single and two speed elevators there is a tripping hazard due to bad levelling if there is only one brake bow functioning. If both brake bows fail then the elevator would run out of control to the top or bottom of the shaft dependant on the loading in the car.

2.2 Parts affected

The MR12 brake bow arm is detailed in the spare parts manual AR 4.8.18 and AS 4.5.34.

2.3 Root causes

The fractures that have been found originate from the casting process and not from normal service.

3 CORRECTIVE ACTIONS

3.1 Corrective action

Each brake bow arm is to be inspected visually at the point marked A in diagram 1. If there are signs of fracture the brake bow is to be replaced.

3.2 Material

3.2.1 Required material

The part number of the brake bow arm is S190030-G1.to be ordered from the factory, see below.



Page: 2

3.2.2 Ordering instructions

Contact Mr W Coxon. - Materials Manager, KONE Lifts, Hounslow.

3.3 Inspection Method

- Stop elevator.
- Carry out inspection on one brake bow at a time.
- Open brake bow. Use service instructions as detailed in section 3.3.3. below.
- Inspect carefully (with a torch) the break bow surface for cracks in the area marked A in Appendix 1.
- Close brake bow arm Use service instructions as detailed in section 3.3.3. below.

SAFETY NOTE: Always isolate machine at main switch before working.

3.3.1 Tools required

2 off 13mm adjustable spanners 1 off torch

3.3.2 Time required

Approx. 1/2 Hour

3.3.3 Replacing and adjusting instructions

Use the service instructions AS 4.5.34 for the detachment of the brake (page 4 section 4) and the mounting of the brake (page 8 section 11).

4 MAINTENANCE

No special maintenance instructions

5 SPECIAL INSTRUCTIONS

No special instructions



Page: 3

APPENDICES

Appendix 1. Diagram of the MR12 and fracture points..





Diagram 2. MR12 Gear





Appendix 2. Feedback form

MR12 BRAKE BOW ARM FEEDBACK FORM					
Complete all information below					
Name					
Country					
Date					
City					
Gear Number (from the gear label)					
Reference Number (from the gear label)					
Erection number					
Date of start in service					
Number of starts when available					
Address to sent the new brake bow arm (by TNT, not a P.O.Box address)					
Office telephone number.					
Office fax number					

FAX for the attention of Mr A J Shiner, Technical Director 0181 754 6285