



Lift and Escalator Industry Association

33-34 Devonshire Street London W1G 6PY
Tel: 020 7935 3013 Fax: 020 7935 3321

E-mail: leia.enquiries@virginnet.co.uk
Website: www.leia.co.uk

9th July 2001

To: All Members
cc: The Quality and Technical Committee (Code No. 434)

Dear Sir/Madam,

**HAMMOND & CHAMPNESS SHEPERD HOME LIFTS
MODELS 36 (JUNIOR) & MODEL 42 (SENIOR)**

Please find enclosed safety bulletin from Thyssen Lifts & Escalators in connection with the slack chain switch operation, where the H&C retrofit overspeed governor kit is fitted.

I trust that you will find this bulletin self-explanatory and be guided accordingly.

Yours faithfully

Robert N Lee
Director, Technical Services



EMTA Awards Limited
Approved Assessment Centre



A company limited by guarantee.
Registered in England N^o 3851206. Registered office as above.



Certificate N^o 42056109



Notification to LEIA Members

**Re: Hammond & Champness Sheperd Home Lifts
Models 36 (Junior) & Model 42 (Senior)**

There is a possibility of H&C Sheperd Home Lifts failing the 5 year LG1 with particular respect to the Slack Chain Switch Operation where the H&C retrofit Overspeed Governor kit is fitted.

Should the slack chain switch arrangement be found to fail Thyssen would advise members that we have a replacement switch kit available from our Leeds Stores. This kit comprises of switches, cams, bracketry, fixings etc along with assembly drawing and parts list.

Slack Chain Switch Kit Part No. TLE 033 SCE 5328

Leeds Stores contact : 0113 2003840