

Lift & Escalator Industry Association

33-34 Devonshire Street London W1G 6PY Tel: 020 7935 3013 Fax: 020 7935 3321

> E-mail: enquiries@leia.co.uk Website: www.leia.co.uk

A growing event - bookings up 50%!



23rd January 2007

To: All Members

cc: The Quality and Technical Committee (Code No. 712)

The Maintenance Committee

Dear member,

SAFETY BULLETIN: E A FOULDS LIMITED

Please find attached Safety Bulletin issued by E A Foulds Limited in connection with the potential malfunction of a particular range of their Flameproof gate locks.

I trust that you will find this bulletin self-explanatory and be guided accordingly.

Yours faithfully

Robert N Lee

Director, Technical Services









E A FOULDS LIMITED ALBERT WORKS • CLIFTON STREET

ALBEHT WORKS • CLIFTON STREET

COLNE • LANCASHIRE • BB8 9AE

TEL: 01282 861500 FAX: 01282 869655

email: info@fouldslifts.co.uk web site: www.fouldslifts.co.uk



Our Ref : EAF/Corus

17th January 2007

Mr. D.M. Fazakerley Director LEIA 33-34 Devonshire Street London W1 1RF

Dear Sir,

During a routine inspection of one of our Flameproof gate locks a sett screw was found to have worked loose. If this had continued the locking plate could have become detached and left the door un-locked and able to be opened when the lift was not there. These locks were manufactured between January 1996 and August 1997 and lie in the number sequence 924 to 986.

These locks can be identified from the previous type by the difference in shape, and from the later type which have a transparent cover and are in one piece.

Please could anyone that services a lift with this type of lock please ensure that the sett screw and two lock nuts, shown on the diagram, are tightened annually and treated with 'Thread Lock'.

Yours faithfully, E A FOULDS LIMITED


E A Foulds Project Director


125

OVER **75** YEARS OF SERVICE









LOCKS WITHOUT PROBLEM

