## **National Association of Lift Makers**

**NALM** 

33/34 Devonshire Street

London W1N 1RF

Director D M Fazakerley

telephone:

0171-935 3013

fax:

0171-935 3321

To: All Members

cc: The Quality and Technical Committee (1983)

20 February 1996

Dear Sir,

## TMS600 Control Systems - Short Circuited Landing Call Light Feed

I enclose a letter received from Kone Lifts Ltd.

This is a little different from the usual circular on such subjects in that the company has indicated it is not feasible to provide a technical specification which will suffice for all types of equipment in service. It is therefore requested members servicing this type of equipment contact the company direct.

Yours faithfully,

D M Fazakerley

Director



25 January 1996

Our Ref:

TSG/JMH

Your Ref:

National Association of Lift Makers 33/34 Devonshire Street London W1N 1RF

## For the attention of Mr D Fazakerly

Dear David

## Re: TMS600 Control Systems - Short Circuited Landing Call Light Feed.

A fault has been discovered on these control systems which may cause uncontrolled movement of the lift.

This fault shall be corrected by a small modification to the controller.

This modification is dependant on the type of hoisting motor drive or hydraulic drive.

The modification details for specific installations can be obtained by forwarding details of the specific site address and TMS600 + drive type(s) to:

KONE Lifts Ltd Engineering Support Group 168-170 Wellington Road South Hounslow Middx TW4 5JN


Tel: 0181 570 7799 Fax: 0181 572 8389

Yours sincerely

A J Shiner

Technical Director

A:LAJS25-1



Ultimate Holding Company:

