

# National Association of Lift Makers

# NALM

33/34 Devonshire Street London W1N 1RF

Director D M Fazakerley

telephone: 0171-935 3013

fax: 0171-935 3321

To: All Members  
cc: The Quality and Technical Committee (1962)

14 December 1995


Dear Sir,

**Highfield Lift Winding Packages fitted with Johnson-Elevanja Pin-Mounted Brake**

We have received the enclosed Engineering Bulletin from Highfield Gears Ltd with the request it be circulated to all members for information.

Please be guided accordingly.

Yours faithfully,



D M Fazakerley  
Director

## ENGINEERING BULLETIN

**Issued by:** Highfield Gears Ltd  
Nile Street  
HUDDERSFIELD  
HD1 3LP

**Tel. 01484 424466**

**Fax. 01484 512433**

**Issued to:** BLA / NALM for general circulation.

**Subject:** JOHNSON-ELEVANJA PIN-MOUNTED BRAKE  
FITTED TO HIGHFIELD LIFT WINDING MACHINES


It has come to our notice that a malassembly may have occurred in a small number of brakes incorporated in the above winding machines, and it is recommended that a check be carried out at the time of the next service visit.

The malassembly concerns the hand release operating cam which is designed to be clear of the solenoid operating plunger in all operating positions but which may be in contact. Where interference is experienced the operating cam should be dressed in the appropriate area to give the aforementioned clearance.

For further information and/or  
rectification guidance, please contact:

Johnson Elevanja Ltd  
Bath Road  
Bridgwater  
Somerset  
TA6 4NU

**For and on Behalf of**  
**HIGHFIELD GEARS LTD**

  
**DAVID CLEGG**  
**Operations Director**