

# National Association of Lift Makers

33/34 Devonshire Street, London W1N 1RF

Director D M Fazakerley

# NALM

Tel: 0171 935 3013

Fax: 0171 935 3321

To: All Members ✓  
cc: Other Possible Interests  
cc: The Quality & Technical Committee (Code No: 1915) ✓ + AEA. + No ISSUES

16 June 1995


Dear Sir

## **DEWHURST PLC, LIFT TECHNICAL BULLETIN No L132**

The above company has asked that we circulate to all members of the Association and other interested parties a copy of their enclosed Bulletin No L132.

Could we please request that you be guided accordingly should you be involved with this type of equipment.

Yours faithfully



D M Fazakerley  
Director

# LIFT TECHNICAL BULLETIN NO: L.132

## ELECTRICAL SAFETY DEVICE FOR PROVING DOORS/GATES CLOSED TYPE CGS CAR GATE SWITCH

### *WARNING OF POTENTIAL SAFETY HAZARD*

A recent site incident, involving a lift user touching a live contact with a finger, has prompted us to highlight the importance of removing electrical power from the car gate switch before: removing the cover, adjusting or otherwise interfering with the switch mechanism or its actuating roller.

### *ACTION REQUIRED*

Fit a warning label on the cover of each car gate switch as shown on the illustration below.

Labels are available, free issue, from the Lift Auxiliaries Team Leader at the Hounslow address shown on this document.

Please ensure that your order clearly identifies your requirements as follows:

Item N°:	002018-000630
Item Description:	WARNING LABEL

### *FUTURE INTENT*

New production will have warning labels fitted during manufacture.

Design improvements will be considered to improve shielding of live electrical parts.

